



**Uwaga**  
L. Niemecki rysunek wyprodukował zgodnie z upz. B. 3115-420-00

Σ = 24356 kg

Uruchomienie kłapy 7612	Nr	Opis	Materiał	Ilość	Waga	Waga	Waga
22	Uruchom kłapy 2250x880	2-266 460	1		1864	Wyk. IV	
21	" 2250x880	2- " 459	1		164	Wyk. IV	
20	" 2250x880	2- " 458	1		1952	Wyk. IV	
19	" 2250x880	2- 286 457	1		1691	Wyk. IV	
18	" 735x880	2- 262 494	1		619	Wyk. III	
17	" 890x740	1- 262 755	1		89	Wyk. III	
16	" 2250x1745	2- 262 509	2		855	Wyk. III	
15	" 2500x800	2- 266 456	1		1995	Wyk. III	
14	" 2500x800	2- " 455	1		1741	Wyk. III	
13	" 2500x800	2- " 454	1		1924	Wyk. III	
12	" 2500x800	2- 266 453	1		168	Wyk. III	
11	" 890x740	2- 262 663	4		51	Wyk. I	
10	Uruchomienie kłapy 5000x780	2- 262 662	2		1791	Wyk. I	
Σ					1791	3582	

16-015-5485

Kłapy 7611	Nr	Opis	Materiał	Ilość	Waga	Waga	Waga
7	Kłapy 735x880	3- 262 650	3	W-18673	27	248	
6	" 890x740	3- 262 648	3	W-18675	85	85	
5	" 2500x800	2- 265 964	4	W-18157	2707	10828	
4	" 2250x1745	2- 262 263	2	W-18653	5375	10750	
3	" 2250x880	2- 265 960	4	W-18158	2867	11548	
2	" 890x740	2- 261 943	4	W-18635	1005	424	
1	Kłapy 5000x780	2- 261 547	2	W-18634	716	1432	

1-266 452

Kłapy i uruchomienia

RACIBORSKA FABRYKA KOTŁÓW W RACIBORZU